HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

BOYER FARM, BARN
Barns of Ebey's Landing National Historical Reserve
711 South Fort Casey Road
Coupeville vicinity
Island County
Washington

HABS WA-245-A

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Anne E. Kidd, photographer, April 2006

WA-245-A-1 PERSPECTIVE WITH LEAN-TO, LOOKING NORTHWEST.

The lean-to on the west façade was removed after it collapsed in severe weather in the late 1990s. The access drive leads to South

Fort Casey Road.

WA-245-A-2 INTERIOR VIEW OF HAY STORAGE, LOOKING NORTH.

The barn is constructed of hand-hewn, 10" square post and beams with mortise and tenon, pegged joints. The photograph also shows the hayfork and track, double doors on the north

façade, and window opening.

WA-245-A-3 NORTHWEST CORNER WITH POST AND BEAM

CONSTRUCTION. The photograph also shows the battens that were added on the interior of the west bay, and the openings for

rafters from the west lean-to.

WA-245-A-4 LEAN-TO INTERIOR, LOOKING EAST. Image shows: ladder

attached to south façade, gate separating hay storage from

animal pens, and east wall construction.